

STATE OF TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION DIVISION OF WATER POLLUTION CONTROL

Compliance Inspection for General NPDES Permit for Storm Water Discharges from Construction Activities (TNR10-0000)

| Construction Site Name: JEFinishers LAT:36.3127 LONG: 88.42. | | | | | | |
|--|------------|----------|--|------------|-----------------------------|-------------|
| ocation: 1630 Brian Patch Lake Rd | | | | | City: Pares | |
| | inty: H | enry | / Total A | cres: | Disturbed Ac | res: 2.5 |
| Name of Permittee (Developer): Jesse and Elmer Yoler Phone: (731)642-6342 | | | | | | |
| Address: 5547 Jones Bend Rd City: Paris | | | | | | |
| Name of Contact: Elmer Yoder Phone: (731) 647-6342 | | | | | | |
| Check List (office & field checks) | Yes | No | | . Co | omments | |
| Has a Notice of Intent (NOI) been submitted? | V_ | | | | | |
| Has a Notice of Coverage (NOC) been issued? | 7, | - | | | | , |
| Has a SWPPP been developed? | V, | | | | | |
| Has the SWPPP been submitted? | V/ | | | | | |
| Have all site contractors signed the NOI? | / | • | | | | ` |
| Have Inspection Reports been filed? | Mr. 3 | boles | not on site | at the | Time of | inspection |
| Are there erosion control measures on-site? | 1 | | seliment (| Constroll | Bern | inspection |
| Is erosion control installed properly and functional? | | | | | | |
| Is there evidence of excessive soil run-off? | | | | | | |
| Is there any impact to streams on or d/s from the site? | | <u> </u> | | | | |
| Are there any ARAP permits required for the site? | | <u> </u> | | | | |
| Are there any ARAP violations? | | | | | | |
| Provided on-Site | | | | | | ر (Check |
| Notice of Coverage for General NPDES Permit for Storm Wa | ter Discha | rges fi | om Construction | Activities | | |
| Storm Water Pollution Prevention Plan (SWPPP) | | | | | | 10 |
| Records of Inspections and Repairs | | | | | | |
| Site Construction at stage where the 2 bouns are in the dry. First quality and vegetative controls should be soon to follow. | | | | | | |
| and resetative controls should be soon to follow. | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| Routine Complaint Follow Up Termination | | | | | | |
| On-Site Contact Print Name: Unaccomfaniel Title: | | | | | | |
| Signature: Date: | | | | | | |
| | | | Date: // 1/0 <i>VE</i> Time: // <i>JO</i> | 9 | Environmental | FO_ |
| Inspector Print Name: TACK Wade Signature: Signature: | | , | Time: 1130 | | For address number see b | |